

In Development

Firmware Version: 0.21

Feature	Products Affected	Workaround	Estimated Implementation
Sequencer not implemented	All Super 6		3 rd Quarter 2020
USB MIDI not implemented	All Super 6	Use MIDI over DIN connectors	4 th Quarter 2020
NRPN transmit/receive not activated	All Super 6	Use MIDI CC	3 rd Quarter 2020
MPE mode not activated	All Super 6		4 th Quarter 2020
MIDI patch dump not activated	All Super 6	Save program and use MIDI Program Change & MIDI Bank Select Messages	4 th Quarter 2020